

BRIDGE CONDITION REPORT

DISTRICT: 6

ROUTE: I-55

COUNTY: SANGAMON

STRUCTURE NUMBER: 084-0107 (NB)
084-0108 (SB)

SECTION: 84-5-2B

JOB NUMBER: D-96-532-03

LOCATION: I-55 OVER BRUSH CREEK

PREPARED BY: COOMBE BLOXDORF P.C.

DATE PREPARED: NOVEMBER, 2003

LETTING DATE: 11/17/06

Table of Contents

Item:	Page:
I. Geographical and Administrative Data	3
II. Physical Description of Structure	3
III. Field Inspection and Physical Evaluation	4
IV. Potential Scope of Work Determination and Analysis	4
V. Discussion and Recommended Scope of Work	4

Attachments:

- A. Location Map
- B. IDOT Master Structure Reports
- C. Bridge Inspection Reports
- D. Cost Analysis
- E. Proposed Structure Drawing and Cross Section
- F. Structure Photos
- G. Hydraulic Analysis Summary
- H. Proposed Plan and Profile
- I. Abbreviated Existing Plans

I. Geographical and Administrative Data

Structure Number:	084-0107 (NB)/ 084-0108 (SB)
County:	Sangamon
Route Carried:	I-55
Feature Crossed:	Brush Creek
Section:	84-5-2B
Station:	550+56.54 (NB); 551+50.15 (SB)
Roadway Classification:	Interstate
Design Speed:	70 mph
ADT (current/design):	14,000 (2001); 18,360 (2021)
ADTT (current):	28% (2001)
Inventory Rating HS:	HS20.0 (NB); HS20.6 (SB)
Operating Rating HS:	HS32.8 (NB); HS35.0 (SB)
Sufficiency Rating:	96.0 (NB); 96.0 (SB)

Construction/Reconstruction/Repair History

These structures were built in 1972 as FAI 55, Section 84-5-2B carrying I-55 over Brush Creek. In 1979, both structures had a bituminous overlay with waterproofing membrane system installed along with neoprene expansion joints at the abutments. In 1990, an expansion joint seal was installed at the north abutment of the southbound structure. In 1992, the northbound structure had an overlay installed on the approach pavements and a new neoprene expansion joint at the south abutment was installed. The structures were scheduled to be overlaid again in 2003 with both expansion joints being replaced at that time.

II. Physical Description of Structure

The existing superstructures consist of six (6) wide flange beams supporting an 8" deck. The existing substructures consist of open abutments founded on steel H-piles and single hammerhead piers founded on spread footings. Rocker-type bearings are used at the abutments and north pier of each structure while fixed bolsters are used at the south pier of each structure. The existing structures are 159'-8" back to back of abutments. The deck is 40'-6" face to face of existing parapets and 44'-0" out to out. Aluminum railing is attached to each parapet. Each structure is skewed 39° 55' right forward. Each structure has been overlaid with a 1½" bituminous overlay and waterproofing membrane system. The existing structures are part of a tangent roadway alignment and are built at the end of a 400' vertical curve having a -1.18% initial slope and a 0% final grade. There are no current utility or other attachments.

III. Field Inspection and Physical Evaluation

The existing structures were visually inspected on December 29, 1999 by District 6 personnel. Copies of the Bridge Inspection Reports are included in this report as Attachment C. The structures have experienced significant overtopping flow resulting in road closures twice since the spring of 2001. Photocopies of photographs taken by the District of this overtopping flow are included in Attachment F. Additionally, photographs of the damage to the deck drains and the debris collected under the structure after the most recent of these events are included in Attachment F. Since the replacement of these bridges is warranted by their hydraulic inadequacy and not their current condition, no further inspection or evaluation of the existing structures is necessary at this time.

Geometric, Horizontal and Vertical Clearance/Hydraulic Data:

The existing structures each carry two 12'-0" lanes of one-way traffic. Each structure has an outside shoulder width of 11'-3" and a median shoulder width of 5'-3" for a total horizontal clearance of 40'-6". A 2'-0" minimum vertical clearance above the HWE₅₀ of 587.9 is shown on the existing plans. There is a structure located on a frontage road directly upstream of the southbound I55 structure.


IV. Potential Scope of Work Determination and Analysis

The hydraulic analysis of the structures contained in a report dated December 2, 2002 prepared by the Bridge Office Hydraulic Unit puts the HWE₅₀ at 591.0. This Hydraulic Report further states that the District would prefer to see a prestressed I-beam superstructure at this location. A bridge length of 185'-0" and a grade raise of approximately 4'-0" are required at this location in order to provide the required minimum vertical clearance above HWE₅₀ and adequate bridge opening. A proposed structure drawing is contained in Attachment E.

V. Discussion and Recommended Scope of Work

Since a complete replacement of both structures is necessary, the District also requested that the cost of an additional lane of traffic in each direction be investigated. Attachment H includes three options for the proposed plan and profile. Option 1 is a two lane roadway with the two lane structures, option 2 is a two lane roadway with the three lane structures and option 3 is a three lane roadway with the three lane structures. Cost estimates of the replacement of the existing structures with two 2-lane structures and two 3-lane structures are shown in Attachment D. These estimates include structure costs only. Traffic crossovers must be used during construction of the new structures since the proposed profile grade will be much higher than the existing.

Attachment A
Location Map



Attachment B

IDOT Master Structure Reports

**Illinois Department of Transportation
Structures Information Management System
Master Structure Report (S-107)**

Date: 5/20/2003
Page 1

Structure Number: 084-0107 **District:** 6

Inventory Data

Facility Carried: I-55 (NB)	Bridge Name: BRUSH CREEK	Sufficiency Rating: 96.0	Structure Length: 159.7
Feature Crossed: WATERWAY	Location: 7 MI S IL 104 INTCHG	HBRRP Eligible: No	AASHTO Bridge Length: 99.9
Bridge Remarks: OPEN - NO RESTRICT	Status Date: 04/1988	Replaced By: 000-00000	Length of Long Span: 57.0
Bridge Status: Open	Parallel Structure: Right	Replaces: 000-00000	Bridge Roadway Width: 40.5
Status Remarks: 	Last Update Date: 12/15/2001	Deck Width: 40.0	Apr Roadway Width: 40.0
Maint County: SANGAMON	Maint Township: 11 DIVERNON	Multi-Level Structure Nbr: 0.0	Sidewalk Width Right: 0.0
Maint Responsibility: I.D.O.T.	Skew Direction: Right	Sidewalk Width Left: 0.0	Skew Angle: 39 D 55 M 00 S
Service On/Under: 1 HIGHWAY	Structure Flared: No	Navigation Control: 0 No	Navigation Horiz Clear: 0
Reporting Agency: I.D.O.T. - BUREAU OF MAINTENANCE	Historical Significance: No	Navigation Vert Clear: 0	Culvert Fill Depth: 0.0
Main Span Matl/Type: STEEL CONTINUOUS	Border Bridge State: Bdr State SN:	Number Culvert Cells: 0	Culvert Cell Height: 0.0
Nbr Of Main Spans: 3	Bdr State % Responsibility:	Culvert Opening Area: 0.0	Culvert Cell Width: 0.00
Approaches	STRUCTURAL STEEL WT:	155,600	RR Vertical Underclear: 00 Ft 00 In
Near #1 Matl/Type: /	Rated By:	2 IDOT	2 ALLOWABLE STRESS
Near #2 Matl/Type: /	Load Rating Date:	08/30/1999	**Railroad Crossing Info**
Far #1 Matl/Type: /	Inventory Rating:	20.0 (256)	Crossing 1 Nbr:
Far #2 Matl/Type: /	Operating Rating:	32.8 (259)	Crossing 1 Nbr:
Median Width/Type: 0 Ft / 0 None	Design Load:	01 HS20+MOD	RR Lateral Underclear:
Guardrail Type / R: 0 None / 0 None	Deck Structure Thickness:	8.0	RR Vertical Underclear:
Toll Facility Indicator: 0 No Toll	Segment:	SouthEast NorthWest	Number Of Lanes:
Latitude: 39° 17' S 34° M 50.17 S	Linked:	One Or Two Way:	One Or Two Way:
Longitude: 89° D 38° M 45.72 S	Natl. Hwy System:	Bypass Length:	Bypass Length:
Deck Structure Type: A: CIP CON NRMLLY FORM	Inventory Direction:	Future ADT Yr/Cnt:	Future ADT Yr/Cnt:
Sidewalks Under Structure: 0 None	Curr AADT Yr/Count:	Designated Truck Rte:	Designated Truck Rte:
	Est Truck Percentage:	Special Systems:	Special Systems:

Key Route On Data

Key Route Nbr: FEDERAL-AID INTERSTATE	Segment:	Y	Station:	003.860
Appurtenances Main Route: 00000	Linked:	On NHS	Segment:	1
Inventory County: 084 SANGAMON	Natl. Hwy System:	N	Station:	00000
Township/Road Dist 11: 00000	Inventory Direction:	North	Segment:	1
Municipality: None	Curr AADT Yr/Count:	2001 / 14000	Linked:	1
Urban Area: None	Est Truck Percentage:	28	Natl. Hwy System:	1
Functional Class: 10 INTERSTATE FAI	Number Of Lanes:	2	Inventory Direction:	1
** CLEARANCES ** South/East North/West	One Or Two Way:	1 One-Way	Curr AADT Yr/Count:	1
Max Rdwy Width: 040.5	Bypass Length:	0	Est Truck Percentage:	1
Horizontal: 042.1	Future ADT Yr/Cnt:	2021 / 18860	Number Of Lanes:	1
Min Vertical: 99Ft 11In	Designated Truck Rte:	CLASS I	One Or Two Way:	1
10 Ft Vertical: 99Ft 11In	Special Systems:	Yes	Bypass Length:	0
Lateral:	Designation	FT FT FT FT FT FT FT	Future ADT Yr/Cnt:	1

Key Route Under Data

Key Route Nbr: 1 Mainline	Segment:	1	Station:	00000
Designation	Linked:	1	Segment:	1
Number	Natl. Hwy System:	1	Station:	00000
Kind	Inventory Direction:	1	Segment:	1
Number	Curr AADT Yr/Count:	1	Linked:	1
Number	Est Truck Percentage:	1	Natl. Hwy System:	1
Number	Number Of Lanes:	1	Inventory Direction:	1
Number	One Or Two Way:	1	Curr AADT Yr/Count:	1
Number	Bypass Length:	0	Est Truck Percentage:	1
Number	Future ADT Yr/Cnt:	2021 / 18860	Number Of Lanes:	1
Number	Designated Truck Rte:	CLASS I	One Or Two Way:	1
Number	Special Systems:	Yes	Bypass Length:	0
Number	Designation	FT FT FT FT FT FT FT	Future ADT Yr/Cnt:	1
Number	Kind	1	Designation	1 Mainline
Number	Number	1	Designation	1 Interstate Highway

**Illinois Department of Transportation
Structures Information Management System
Master Structure Report (S-107)**

Date: 5/20/2003
Page 2

Structure Number: 084-0107

District: 6

Data Related to Inspection Information

*****Inspection Intervals *****

Routine NBIS: 24 MOS Underwater: 24 MOS Combination Type 3S-1: Tons
Fracture Critical: 0 MOS Special: 0 MOS Combination Type 3S-2: Tons

Inspection Date:

01/08/2003

Special Inspection Date:

GOOD CONDITION - SOME MINOR PROBLEMS

SATISFACTORY CONDITION - MINOR DETERIORATION

7 GOOD CONDITION - SOME MINOR PROBLEMS

NOT APPLICABLE

6 SATISFACTORY CONDITION - MINOR DETERIORATION

6 EQUAL TO PRESENT MINIMUM CRITERIA

7 BETTER THAN PRESENT MINIMUM CRITERIA

N NOT APPLICABLE

6 EQUAL TO PRESENT MINIMUM CRITERIA

8 EQUAL TO PRESENT DESIRABLE CRITERIA

2 Doesn't Meet Standards

232 Not Acceptable Acceptable Not Acceptable

N/A

Deck:

Superstructure:

Substructure:

Culvert:

Channel and Protection:

Structural Evaluation:

Deck Geometry:

Underclearance-Vert/Lat:

Waterway Adequacy:

Approach Roadway Align:

Bridge Railing Appraisal:

Approach Guardrail:

Pier Navig Protection:

Temperature:

45

D.COPENBARGER

Appraised By:

NO PROBLEMS NOTED.

Inspected By:

0

Inspection Remarks:

Fracture Critical Members:

0

Microfilm Data Recorded:

Yes

Actual Posted Limits ***

Combination Type 3S-1: Tons

Combination Type 3S-2: Tons

Bridge Posting Level:

5 No Posting Required

Single Unit Vehicles:

N/A

Combination Type 3S-1:

N/A

Combination Type 3S-2:

N/A

One Truck At A Time:

N/A

Tons

One Truck:

N/A

Tons

Actual Posted Limits ***

Tons

One Truck At A Time:

N/A

Tons

AT

LD SHP PRM GRN FNL

FLD ZINC & ACRYLIC

Last Paint Type:

BITUMINOUS OVERLAY

Deck Wearing Surf:

G WATERPROOF MEM SYST

Deck Membrane:

J NONE

Deck Protection:

N/A

Total Deck Thick:

09.5

Last Paint Date:

09/1994

Inspection Remarks:

N/A

Underwater Inspection/Appraisal Information

Scour critical

Probe

Visual

Inspection Category:

36 Restricted

V.P.

Inspection Method:

45

Appraisal Rating:

7

GENERALLY GOOD - MINOR REPAIR POSSIBLE

Analysis By:

GORDON BENSON

Scour Critical Information

CALCULATED SCOUR ACCEPTABLE

Evaluation Method:

12/27/1993

Analysis By:

N/A

Construction Information

1972 Original

1979 Reconstructed

FAI 55 Sta: 550+56.54

1978 D6 WMS Sta: 550+56.54

Year:

FAI 55

84-5-2B

Contract Nbr:

Fed Aid Pr #:

1 0552044076

Built By:

1 D.O.T.

Waterway Information

0 YRS Drainage Area:

0 SF

Flood Base Q (CFS):

0

Flood Design Nat H W E:

0

Flood Des Open Prop:

0

Miscellaneous

Fracture Critical Members:

0

Microfilm Data Recorded:

Yes

Proposed Improvement

Length:

Cost Estimate Year:

Type of Work:

Done By:

Remarks:

Bridge Cost:

Roadway Cost:

Total Project Cost:

**Illinois Department of Transportation
Structures Information Management System
Master Structure Report (S-107)**

Date: 5/20/2003
Page 1

Structure Number: 084-0108 **District:** 6

Inventory Data

Facility Carried:	I-55 (SB)	Bridge Name:	BRUSH CREEK	Sufficiency Rating:	96.0	Structure Length:	159.7
Feature Crossed:	7M S IL 104 INTCHG	Location:	7M S IL 104 INTCHG	HRRP Eligible:	No	AASHTO Bridge Length:	99.9
Bridge Remarks:	1 OPEN • NO RESTRICT	Status Date:	04/1988	Replaced By:	000-00000	Length of Long Span:	57.0
Bridge Status:				Replaces:	000-00000	Bridge Roadway Width:	40.5
Status Remarks:				Last Update Date:	12/15/2001	Abpr. Roadway Width:	40.0
Maint County:	084 SANGAMON	Maint Township:	11 DIVERNON	Parallel Structure:	Left	Deck Width:	44.0
Maint Responsibility:	01 I.D.O.T.	Service On/Under:	1 HIGHWAY	Multi-Level Structure Nbr:		Sidewalk Width Right:	0.0
Reporting Agency:	1 I.D.O.T. - BUREAU OF MAINTENANCE	Main Span Mat/Type:	4 STEEL CONTINUOUS	Skew Direction:	Right	Sidewalk Width Left:	0.0
Nbr Of Main Spans:	3	Nbr Of Approach Spans:	0	Skew Angle:	39 D 55 M 00 S	Navigation Control:	0 No
Approaches				Structure Flared:	No	Navigation Horiz Clear:	0
Near #1 Mat/Type:	/	Near #2 Mat/Type:	/	Historical Significance:	No	Navigation Vert Clear:	0
Far #1 Mat/Type:	/	Far #2 Mat/Type:	/	Border Bridge State:		Culvert Fill Depth:	0.0
Median Width/Type:	0 Ft. / 10 ft None	Guardrail Type L/R:	0 None / 0 None	Bdr State SN:		Number Culvert Cells:	0
Toll Facility Indicator:	0 No Toll	Segment:	Y	Bdr State % Responsibility:	0	Culvert Opening Area:	0.0
Latitude:	39 D 34 M 49.631 S	Linked:		Structural Steel Wt:	155,600	Culvert Cell Height:	0.00
Deck Structure Type:	A CIP CON NRMLY FORM	Natl. Hwy System:	On NHS	Deck Structure Thickness:	8.0	Culvert Cell Width:	0.00
Sidewalks Under Structure:				Rated By:	2 IDOT	Rate Method:	2 ALLOWABLE STRESS
				Inventory Rating:	(20.6) (237)	Load Rating Date:	08/30/1999
				Operating Rating:	35.0 (263)	**Railroad Crossing Info**	
				Design Load:	01 HS20-MOD	Crossing 1 Nbr:	
				Deck Structure Thickness:	8.0	Crossing 1 Nbr:	
						RR Lateral Underclear:	0.00
						RR Vertical Underclear:	00 Ft 00 In
Key Route Under Data							
Key Route Nbr:	FEDERAL AID INTERSTATE	Station:	003.850	Segment:		Station:	
Appurtenances	Main Route	0055	Segment:		Segment:		Segment:
Inventory County:	084 SANGAMON	Station:	003.850	Linked:		Natl. Hwy System:	
Township/Road Dist	11 DIVERNON	Segment:		Natl. Hwy System:	Y	Inventory Direction:	
Municipality	00000	Segment:		Inventory Direction:		Curr AADT Yr/Count:	/
Urban Area:	None	Segment:		Curr AADT Yr/Count:		Est Truck Percentage:	/
Functional Class:	10 INTERSTATE, FAI	Segment:		Est Truck Percentage:		Number Of Lanes:	
** CLEARANCES ** South/East North/West				Number Of Lanes:	2	One Or Two Way:	
Max Rdwy Width:	040.7	1 [One-Way]		Bypass Length:		Bypass Length:	
Horizontal:	042.0	0		Future AADT Yr/Cnt:		Future AADT Yr/Cnt:	/
Min Vertical:	99 Ft	00 Ft	In	Designated Truck Rte:		Designated Truck Rte:	
10 Ft Vertical:	99 Ft	11 Ft	In	Special Systems:		Special Systems:	
Lateral:	99 Ft	11 Ft	In				
Marked Route On Data ***							
Route #1:	1 Mainline	Designation:	1 Interstate Highway	Number:	0055	Kind:	
Route #2:							
Route #3:							
Marked Route Under Data ***							
Designation:		Number:		Kind:		Number:	

Attachment C
Bridge Inspection Reports

Bridge Inspection Report SN 084-0107

12/30/99

B-Smart Project
SN 084-0107
FAI 55 NB
84-5-2B
BRUSH CREEK
0.7MI S I-55/IL104 INT
Sangamon County

This structure was visually inspected on December 29, 1999, to determine its physical condition and recommendations for replacement or rehabilitation. The inspection concentrated on accessible portions of the bridge.

This structure, built in 1972, is a three span steel continuous multi-beam structure with open stub abutments. It has an overall length of 159.7 feet, measured from back to back of abutments, and a measured bridge roadway width of 40.5 feet. It carries FAI 55 NB over Brush Creek and is located 0.7 mile South of the I-55/IL104 interchange in Sangamon County.

Reconstruction History:

- 1). 1979 – Bituminous overlay and waterproof membrane system and new neoprene expansion joints.
- 2). 1992-Bituminous approach overlay at both abutments and new neoprene joint at south abutment.

A routine NBIS inspection conducted on January 7, 1999, rates the deck 7 (good condition), superstructure 6 (satisfactory condition) and the substructure 7 (good condition). The structure has an overall structural condition of 6 (equal to present minimum criteria). It is currently rated at 36 gross tons (HS 20.1) at the inventory stress level and at 59 gross tons (HS 32.9) at the operating stress level. The current sufficiency rating is 96.

Inspection Year	Deck	Superstructure	Substructure
1988	7	7	7
1993	7	6	7
1997	7	6	7

Findings:

- The bituminous wearing surface has heavy map cracking throughout. The deck soffit is generally in good condition with minor hairline transverse cracking throughout. There are minor delaminations around a few drains.

- The concrete parapets are generally in good condition with light cracking. The aluminum rail is in good condition.
- The steel beams show light to moderate rusting on the interior beams. The beam ends and fascias were painted in 1995 are in fair condition with minor rusting.
- The bearings at the abutments are heavily rusted with some section loss. The bearings at the piers are in good condition.
- All floor drains have previously been extended but were not supported from the fascia beam. There are 15 floor drain extensions missing.
- The north neoprene expansion joint at the north abutment has 12' of damaged hold down blocks. The joint is leaking. The south neoprene expansion joint is leaking slightly.
- The north abutment backwall has light map cracking at both wing junctions. There is one horizontal crack in the top portion of the cap.
- The south abutment backwall has light map cracking at both wing junctions.
- The piers are in good condition.
- The channel alignment is fair with the stream flowing along the south side to the north pier. There are no scour problems.
- The north approach has slight settlement.

Recommendations:

This project meets the requirements of a B-Smart project. As follows is the recommended work:

- Remove the bituminous wearing surface and waterproof membrane system and replace with 2 ¼" minimum microsilica wearing surface. It is estimated that there will be 10 sq. yd. (1.3%) of full depth patching and 30 sq. yd. (4%) of partial depth patching.
- Replace the bearings at both abutments.
- Remove the neoprene expansion joint seals and hold down blocks at both abutments. The concrete adjacent to the joint at the end of the deck and on the approach needs replaced at the north abutment only. Install polymer nosing and silicone joint sealer at both abutments.
- Plug every other deck drain and drains over substructure units. Replace missing drain extensions if not plugged and add support to bottom flange of fascia beam on all extensions to remain in place.
- Both approaches need overlayed out 100' from the abutments. This work should be included with roadway resurfacing.
- The guardrail needs updated.

Attached to this report are the latest NBIS/Pontis inspection reports with comments, economic analysis and two sets of photographs.

DAC

Start: 1/21/99

End: 1/21/99

Remarks: *Local Load*

0840107

28-Dec-98

7MI S I-55/IL104INT

FAI 55 NB

RDWY WOTS	40.5 FT	FAI 55	84-5-2B	1991	Inspect Date	1-21-99
STR LNGTH	159.7 FT	FAI 55	1978 D6 WMS	1979	Temperature	58
DK WDTH	44 FT	FAI 55	84-5-2B	1972	Inventory Loading	
Main Spans	3				Tons	20
App Spans	0				Prog Yr	Out
WGT STR STL	155600	Paint	9409AT		Contract #	0
THICKNESS	8 9.5	Last Insp	970106			
HANDRAIL	1 Alum Oval on Con	Interval	24	MicroFilm	6-185	6-70,118 0 0
ABUT TYPE	Open Stub	SKEW	395500		ADT On/Under	2286 0
PIER TYPE(s)	Hammerhead 0	WEARING SURF, MEMBRANE, DECK PROTECTION			ADT On/ Under	12700 0
OPEN BRG	0 0	SURF C	GAJ	BITUMINOUS OVERLAY, WMS, NONE	Year	95
CLOSED BRG	12A 0	MATL C	402	STEEL CONTINUOUS STRINGER/MULTI-BEAM/WF BEAM	SCOPE OF WORK	
NO JOINT	6A 6J	Suff #	98	STA 1550+56.54 N Culvert	7 DECK FAI 55 Resurfacing	
PAINT CO	Field Applied Zinc Silicate & Acrylic				6 SUPER	
					7 SUB Overall	6

Sn-15 000.084-0107.25621

DECK

Wearing Surface	3
Deck Structure Cond	4
Curbs	
Median	
Sidewalks	
Parapet	
Railing	4
Leaching Thru Cracks	3
Soffit	✓
Drains	3
Light Standards	
Joint Leakage	2
Exp Jts or Devices	2
Item # 58	
Inspectors Rtg	7

SUPERSTRUCTURE

Bearing Devices	3
Stringers	
Girders or Beams	3
Floorbeams	
Diaphragms/Braces	3
Crack Leaching	
Joints/leakage-Condition	
Trusses	
Portals& Bracing	
Chords	
Paint	3
Drainage Systems	
Rivets or Bolts	3
Weld Conditions	
Rust Worst % Lost	3
Conc Crack/Spall/Scaling	
Collision Damage	✓
LL Deflection/Vibration	3
Alignment of Members	3
Inspectors Rtg	6

SUBSTRUCTURE**Abutment-Wings**

Backwall	
Bearing Seats	
Breastwall	
Footings	
Erosion/Slopes	
Settlement	
Pile Bent Abut-Wings	3
Backwalls	3
Caps	3
Bearing Seats	
Piles	
Erosion/Slopes	3
Settlement	4
Piers-Caps	4
Columns	4
Crashwalls	
Footings	
Settlement	4
Pile Bent Pier-Caps	
Piles	
Settlement	
Conc Crack/Spall/Scaling	3

Approach Roadway Condition

Approach Slab	3
Settlement	3
Expansion Joints	Item # 59
Approach-Guardrail	3
Pavement	3
Shoulders	3
Embankment	3
Drainage Items	
Item # 65	
Inspectors Rtg	6

Channel & Chanel Protection

Channel Scour	3
Erosion of Banks	3
Drift	✓
Vegetation	3
Channel Alignment	3
Fender System	
Spur Dykes&Jetties	
Rip-rap	
Concrete Slopewall	3
Inspectors Rtg	16

Approach Roadway Alignment

Riding Quality	3
Settlement	3
Structural Condition	3
Inspectors Rtg	8
Waterway Adequacy	

Culvert

Headwalls	
Top Slab	
Interior Walls	
Side Walls	
Wingwalls	
Floor	
Railing	
Siltation	
Settlement	
Scour	
Item # 62	
Inspectors Rtg	N/A

Railing Appraisal

Item # 36 Inspectors Rtg

2121212

Inspectors Signature

Charles Loh

1-21-99

1-Needs Replacement 2-Poor 3-Fair 4-Good 5-New

Inspectors Signature

Jan 7, 1999

354-0107

Bld. Wearing Surface has heavy map cracking throughout.

North exp. Joint is in poor condition, with $\pm 12'$ showing damaged blocks. Joint has mod. leakage.

concrete parapets show light hairline vertical cracking. Alum rails are in good condition.

Deck soffit has minor hairline transverse cracking throughout. Good Condition. Minor delaminations around a few drains.

steel beams show light to moderate rusting on interior beams. Repainted beam ends look good.

North abut. backwall has light map cracking at both wing jet. Some scaling noted at west wing jet. (1) horizontal crack noted in top portion of the cap.

North pier OK

South pier cap has (1) small delamination on north side.

South abut. backwall/wing jets show light map cracking. Light scaling noted at west jet.

channel alignment for stream flows along south side of North pier.

North app. has slight settlement.

* 12 drain extensions missing at south abut.

* North exp. Jt damaged Neoprene blocks torn ± 12 LF (loose)

Equipment

0

Remarks

0

Start:

End:

0840107

28-Dec-96

Traffic Control:

0

FAI 55 NB

.7 MI S I-55/L104 INT

BRUSH CREEK

Past Insp Time:

0

ROW/WDTH

40.5 FT

STR LNGTH

159.7 FT

DK WDTH

44 FT

Main Spans

3

App Spans

0

WGT STR STL

155600

No Posting

Utilities

NNN

Paint 9409AT

THICKNESS

8

9.5

Last Insp 970106

Interval 24

HANDRAIL

1 Alum Oval on Conc

ABUT TYPE

Open Stub

PIER TYPE(s)

Hammerhead

OPEN BRG

0

CLOSED BRG

12A

NO JOINT

6A

PAINT CD

Field Applied Zinc Silicate & Acrylic

FAI 55 84-5-2B 1991
FAI 55 1978 D6 WMS 1979
FAI 55 84-5-2B 1972Inspect Date 1-7-99
Temperature 8°
Inventory Loading
Tons 20
Prog Yr Out
Contract # 0

MICROFILM 6-185 6-70,118 0 0

SKEW 395500 WEARING SURF, MEMBRANE, DECK PROTECTION ADOT On/Under 2286 0
ADT On/Under 12700 0BITUMINOUS OVERLAY, WMS, NONE Year 95
STEEL CONTINUOUS STRINGER/MULTI-BEAM/WF BEAM SCOPE OF WORK.STA 550+56.54 N Culvert 7 DECK FAI 55 Resurfacing
6 SUPER
7 SUB Overall 6

Sn-15 000.084-0107.25621

Bams Tables

Enviroment Deck Super Sub

4 4 1

Quantity in State (%)

Element	Description	Comments	Env	Qty	Units	1	2	3	4	5
14	CONCRETE DECK PROTECTED W/A/C OVERLAY		4	6840	SF	108	6387			21
107	Lead Painted Steel Open Girder		4	9653	SF	373	338			
172	Lead Painted Steel Closed Web/Box Girder & Open		4	12	EACH	12				
210	Concrete Pier Wall		1	1780	SF	1780				
215	Concrete Abutment		1	1026	SF	15	6			
234	Concrete Pier Or Abutment Cap		1	235	LF		3			
307	Neoprene Expansion Joint		4	58	LF	58		28	12	
308	Continuos Seal Neoprene Expansion Joint		4	58	LF					
311	Moveable Steel Brgs below Discontinuous Dk Jts		4	12	EACH	9				
313	Fixed Bearing		4	6	EACH	6				
316	Moveable Steel Bearings below Continuous Decks		4	6	EACH	6				
323	Approach Pavement		4	2	EACH	1				
331	Concrete Bridge Railing		4	311	LF	311				
361	Pier and Abutment Scour		1	1	EACH	1				

EXANS. JT, MEAS

S' TEMP

E - W

No. Aout. 2 1/8" - 2"



So. Engt. 2 3/8" - 2"

ENTRANCE



1-1-94

(RK)

SIRHCUHE NO. 084-0107



STRUCTURE NO. 084-0127





$$\begin{array}{r} 215 \\ \hline C2 \\ 12 \\ 2 \\ 2 \\ 2 \\ \hline 18 \end{array}$$

$$\begin{array}{r} 234 \\ \hline C3 \\ 1 \\ 3 \\ 2 \\ \hline 6 \end{array}$$

16 beams required

STRUCTURE NO. 054-0107
S. P. er



234
C 3 1

ESTIMATE OF COST

SN # 084-0107
 Location .7MI S I-55/IL104INT
 Route: FAI-55 NB
 Feature X: BRUSH CREEK

ADT

Rev
14-Jan-2000

Item #	Description	COST	Unit	QTY	TOTAL
Z0006110	BRIDGE DECK MICROSILICA CONCRETE OVERLAY	50	SQ YD	720	36000
Z0006200	CONCRETE BRIDGE DECK SCARIFICATION	6.1	SQ YD	720	4392
Z0016001	DECK SLAB REPAIR (FULL-DEPTH, TYPE I)	400	SQ YD	40	16000
Z0016200	DECK SLAB REPAIR, (PARTIAL)	200	SQ YD	80	16000
44000910	BITUMINOUS CONCRETE REMOVAL (DECK)	5.3	SQ YD	720	3816
50102400	CONC REM	600	CU YD	8	4800
X0320887	POLYMER CONCRETE NOSINGS	550	CU FT	13	7150
X0301424	SILICONE JOINT SEALER	40	LIN FT	115	4600
50300255	CONCRETE SUPER STRUCTURES(Parapet=0.1CY/ft)	600	CU YD	8	4800
50300260	BRIDGE DECK GROOVING	4	SQ YD	720	2880
50300530	FLOOR DRAIN EXTENSIONS	300	EACH	15	4500
50800205	REINFORCEMENT BARS, EPOXY COATED(deck)8Lbs/SF	0.8	LB	3000	2400
70100405	TRAFFIC CONTROL & PROTECTION STANDARD 701321	15000	EACH	1	15000
70400100	TEMP CONC BARRIER (Deck 12:1)	18	LIN FT	500	9000
70400200	REL TEMP CONC BARRIER	4.5	LIN FT	500	2250
70400300	TEMP CONC BAR TERM SEC	200	EACH	4	800
	Traffic Barrier Terminal, Type 1 Special	2000	Each	4	8000
50300320	ELASTOMERIC BEARING ASSEMBLY TY II	900	EACH	12	10800
50500715	JACK AND REMOVE EXISTING BEARINGS	850	EACH	12	10200

Scope

Remove bituminous, patch deck and place microsilica overlay

0

New bearings at both abutments

0

Remove the Neoprene joint seal and replace with polymer nosing and silicone both Abuts

0

At the north abutment replace the concrete adjacent to the joint

0

Drain extensions

163388

Note: Cost of overlaying approaches and upgrading guardrail not included.

Add 10%

\$179,727

To be included with roadway cost (resurfacing project).

Total Cost

45 \$ per Sq Ft

Length	160 (Est length of new structures)
Width	44
Deck Replacement Cost (for Comparison Only)	\$316,800

Bridge Inspection Report SN 084-0108

12/30/99

B-Smart Project
SN 084-0108
FAI 55 SB
84-5-2B
BRUSH CREEK
0.7MI S I-55/IL104 INT
Sangamon County

This structure was visually inspected on December 29, 1999, to determine its physical condition and recommendations for replacement or rehabilitation. The inspection concentrated on accessible portions of the bridge.

This structure, built in 1972, is a three span steel continuous multi-beam structure with open stub abutments. It has an overall length of 159.7 feet, measured from back to back of abutments, and a measured bridge roadway width of 40.5 feet. It carries FAI 55 SB over Brush Creek and is located 0.7 mile South of the I-55/IL104 interchange in Sangamon County.

Reconstruction History:

- 1). 1979 - Bituminous overlay and waterproof membrane system and new neoprene expansion joints.
- 2). 1990 - Pavetech expansion joint seal installed at north abutment

A routine NBIS inspection conducted on August 31, 1998, rates the deck 7 (good condition), superstructure 7 (good condition) and the substructure 7 (good condition). The structure has an overall structural condition of 7 (better than minimum present minimum criteria). It is currently rated at 37 gross tons (HS 20.6) at the inventory stress level and at 63 gross tons (HS 35) at the operating stress level. The current sufficiency rating is 96.

Inspection Year	Deck	Superstructure	Substructure
1988	7	8	8
1993	7	6	7
1996	7	6	7

Findings:

- The bituminous wearing surface has heavy map cracking throughout. The deck soffit is generally in good condition with minor hairline transverse cracking throughout. There are minor delaminations around a few drains.
- The concrete parapets are generally in good condition with light cracking and a few small spalls. The aluminum rail is in good condition.

- The steel beams show light to moderate rusting on the interior beams. The beam ends and fascias were painted in 1995 are in fair condition with minor rusting.
- The bearings at the abutments are heavily rusted with some section loss. The bearings at the piers are in good condition.
- All floor drains have previously been extended but were not supported from the fascia beam. There are 15 floor drain extensions missing.
- The north expansion joint is a Pavetech joint installed in 1990. It is starting to break up and leak.
- The neoprene joint at the south abutment has several sections of missing hold down blocks. The joint is leaking and in poor overall condition.
- The north abutment backwall has light map cracking.
- The south abutment backwall has map cracking with efflorescence at both wing junctions.
- The piers are in good condition.
- The channel alignment is good. There are no scour problems.
- Both approaches have moderate settlement.


Recommendations:

This project meets the requirements of a B-Smart project. As follows is the recommended work:

- Remove the bituminous wearing surface and waterproof membrane system and replace with 2 $\frac{1}{4}$ " minimum microsilica wearing surface. It is estimated that there will be 10 sq. yd. (1.3%) of full depth patching and 30 sq. yd. (4%) of partial depth patching.
- Replace the bearings at both abutments.
- Remove and replace the concrete adjacent to the joint at the end of the deck and on the approach at both abutments
- Remove the neoprene expansion joints seals. Install polymer nosing and silicone joint sealer at both abutments.
- Plug every other deck drain and drains over substructure units. Replace missing drain extensions if not plugged and add support to bottom flange of fascia beam on all extensions to remain in place.
- Both approaches need overlayed out 100' from the abutments. This work should be included with roadway resurfacing.
- The guardrail needs updated.

Attached to this report are the latest NBIS/Pontis inspection reports with comments, economic analysis and two sets of photographs.

DAC



August 31 1973

334-573

P. t. wearing surface is map cracked throughout entire area.

South abut neoprene joint has $\frac{1}{2}$ section missing near E.

concrete piers show light to moderate hairline vertical cracking throughout. A few small spots to shallow robes noted along East side.

Deck soffit has minor hairline transverse cracking with rust staining.

steel beams have moderate rusting on bottom of bottom flanges throughout. Moderate rusting on abut rockers.


South abut backwall has light map cracking with effl. leaching.

Both piers are in good condition.


North abut backwall has minor hairline vertical cracking. Channel alignment good.

both app slabs show moderate settlement.

STRUCTURE NO. 084105




NORTH ABUTMENT



SCRUB ABUTMENT

#215
C3
18

STRUCTURE NO. 0840108



ESTIMATE OF COST

SN # 084-0108
 Location .7MI S I-55/IL104INT
 Route: FAI-55 SB
 Feature X: BRUSH CREEK

ADT

Rev
 14-Jan-2000

Item #	Description	COST	Unit	QTY	TOTAL
Z0006110	BRIDGE DECK MICROSILICA CONCRETE OVERLAY	50	SQ YD	720	36000
Z0006200	CONCRETE BRIDGE DECK SCARIFICATION	6.1	SQ YD	720	4392
Z0016001	DECK SLAB REPAIR (FULL-DEPTH, TYPE I)	400	SQ YD	40	16000
Z0016200	DECK SLAB REPAIR, (PARTIAL)	200	SQ YD	80	16000
44000910	BITUMINOUS CONCRETE REMOVAL (DECK) use when a	5.3	SQ YD	720	3816
50102400	CONC REM	600	CU YD	16	9600
X0320887	POLYMER CONCRETE NOSINGS	550	CU FT	13	7150
X0301424	SILICONE JOINT SEALER	40	LIN FT	115	4600
50300255	CONCRETE SUPER STRUCTURES(Parapet=0.1CY/ft)	600	CU YD	16	9600
50300260	BRIDGE DECK GROOVING	4	SQ YD	720	2880
50300530	FLOOR DRAIN EXTENSIONS	300	EACH	15	4500
50800205	REINFORCEMENT BARS, EPOXY COATED(deck)8Lbs/SF	0.8	LB	3000	2400
70100405	TRAFFIC CONTROL & PROTECTION STANDARD 701321	15000	EACH	1	15000
70400100	TEMP CONC BARRIER (Tabor 12:1)	18	LIN FT	500	9000
70400200	REL TEMP CONC BARRIER	4.5	LIN FT	500	2250
70400300	TEMP CONC BAR TERM SEC	200	EACH	4	800
	Traffic Barrier Terminal, Type 1 Special	2000	Each	4	8000
50300320	ELASTOMERIC BEARING ASSEMBLY TY II	900	EACH	12	10800
50500715	JACK AND REMOVE EXISTING BEARINGS	850	EACH	12	10200

Scope

Remove bituminous, patch deck and place microsilica overlay	0
New bearings at both abutments	0
Remove the Neoprene joint seal and replace with polymer nosing and silicone both abuts	0
At both abutments replace the concrete adjacent to the joint	0
Drain extensions	172988
Update guardrail terminals	Add 10% \$190,287
Note: Cost of overlaying approaches and upgrading guardrail not included.	
To be included with roadway cost (resurfacing project).	

45 \$ per Sq Ft

Length
 Width

160 (Est length of new structures)

44

Deck Replacement Cost (for Comparison Only)

\$316,800

Attachment D

Cost Analysis

ESTIMATE

SN: 084-0107 (NB)

084-0108 (SB)

Route: FAI 55

Location: I-55 over Brush Creek

Scope: Remove existing structures and replace
with two 2-lane structures

Item	Unit	Unit		
		Cost	Quantity	Total
Structure Excavation	cu yd	20	792	15,840
Concrete Superstructure	cu yd	700	572	400,400
Concrete Structures	cu yd	600	524	314,400
Protective Coat	sq yd	2	1,980	3,960
Bridge Deck Grooving	sq yd	10	1,510	15,100
Reinforcement Bars, Epoxy Coated	lb	1	182,800	182,800
Furnishing and Driving Steel Piles	ft	25	2,536	63,400
Prestressed I-Beams, 42"	ft	90	2,160	194,400
Porous Granular Embankment	cu yd	30	472	14,160
Stone Riprap, Class A4	sq yd	60	2,150	129,000
Filter Fabric for Use With Riprap	sq yd	2	2,150	4,300
Bridge Joint System (Expansion)	ft	40	226	9,040
Elastomeric Bearing Assembly	each	600	24	14,400
Bridge Seat Sealer	sq ft	4	620	2,480
				<u>1,363,680</u>

Note:

This cost estimate does not include costs associated with the grade raise or the traffic crossovers.

ESTIMATE

SN: 084-0107 (NB)

084-0108 (SB)

Route: FAI 55

Location: I-55 over Brush Creek

Scope: Remove existing structures and replace
with two 3-lane structures


Item	Unit	Unit		
		Cost	Quantity	Total
Structure Excavation	cu yd	20	1,088	21,760
Concrete Superstructure	cu yd	700	784	548,800
Concrete Structures	cu yd	600	720	432,000
Protective Coat	sq yd	2	2,710	5,420
Bridge Deck Grooving	sq yd	10	2,068	20,680
Reinforcement Bars, Epoxy Coated	lb	1	248,000	248,000
Furnishing and Driving Steel Piles	ft	25	3,432	85,800
Prestressed I-Beams, 42"	ft	90	2,880	259,200
Porous Granular Embankment	cu yd	30	650	19,500
Stone Riprap, Class A4	sq yd	60	2,660	159,600
Filter Fabric for Use With Riprap	sq yd	2	2,660	5,320
Bridge Joint System (Expansion)	ft	40	310	12,400
Elastomeric Bearing Assembly	each	600	32	19,200
Bridge Seat Sealer	sq ft	4	850	3,400
				1,841,080

Note:


This cost estimate does not include costs associated with the grade raise or the traffic crossovers.

Attachment E

Proposed Structure Drawing and Cross Section




ELEVATION




NOTE

The number and location of piers, the profile and the bridge length are subject to refinement in final design.




PLAN
(Showing NB Lanes)



CROSS SECTION
(Showing NB Lanes)

PROPOSED
STRUCTURE DRAWING
THREE LANE
STRUCTURES




ELEVATION


NOTE



The number and location of piers, the profile and the bridge length are subject to refinement in final design.



PLAN
(Showing NB Lanes)



CROSS SECTION
(Showing NB Lanes)

PROPOSED
STRUCTURE DRAWING
TWO LANE
STRUCTURES

Attachment F
Structure Photos

Attachment G
Hydraulic Analysis Summary



Illinois Department of Transportation

Memorandum

To: Victor A. Modeer Attn: W. E. Martens
From: Ralph E. Anderson By: Todd E. Ahrens
Subject: Hydraulic Report *Todd E. Ahrens*
Date: December 2, 2002

REC'D DIST. 6
DEC 11 2002
STUDIES & PLANS

FAI Route 55 (I-55)
Morgan County

D-96-024-99
SN 084-0107 (FAI 55NB)
SN 084-0108 (FAI 55 SB)
SN 084-0002 (US 66)

I-55 over Brush Creek

We have reviewed the Hydraulic Report for the dual structures listed above. The report relates this high profile location has experienced significant overtopping flow resulting in road closure twice since the spring of 2001. Your attached memo suggests those events could be attributed to an anomalous rainfall pattern and that likely floodplain development upstream promises increased runoff. After discussions with your hydraulic staff and others, it is clear the undersized frontage road bridge just upstream is a major contributing factor. It is also clear that the District wants to give consideration to any alternative at this crossing that will reduce the frequency and magnitude of future overtopping flow. For this reason, we have developed seven different waterway information tables. They reflect proposed conditions ranging from the minimum improvement required to meet design \ regulatory requirements to a set of three new, multi-span bridges that minimize backwater for the regulatory Q100 event. They also model the impact of removing or replacing the frontage road structure. The tables and supporting notes are attached.

Your submittal memo, dated September 26, 2002, requested that we utilize the FIS discharges as the basis for our hydraulic recommendations. The Hydraulic Report (HR) consultant had supported that position by calibrating the discharges within the HEC-RAS model to produce water surface profiles in agreement with those observed during this spring's flooding. Although the calibrated discharges are roughly equivalent to FIS values, they are double the magnitude of the conventional USGS estimates that are utilized by all of the approved tables.

We feel the USGS regression analysis is the appropriate hydrologic method here. Primarily, this is due to the fact we were able to construct a HEC-RAS model utilizing the lower USGS numbers that still produces water surface profiles approximately equal to those observed. The attached notes detail the

adjustments made to the HEC-RAS model and also more of our thinking behind the discharge selection. In general, it is widely recognized that FIS values are ultra-conservative. In this case, FIS discharges are produced by a relatively obscure hydrologic method that has not been commonly employed for design purposes since sometime in the 1970's. Consistency and uniformity of design review dictate that we employ our standard hydrologic method, if the discharges can form the basis of a realistic hydraulic model reflective of past flood events. We feel the attached waterway information tables meet that standard. However, we do want to stress that this project will require an Individual Permit that can only be issued by the Illinois Department of Natural Resources-Office of Water Resources (IDNR-OWR) and that during their review they could request revisions be made to the proposed bridges.

We concur with a primary conclusion in the HR. Removal or replacement of the frontage road bridge just upstream is the most effective way to lower water surface profiles at I-55 and reduce the bridge length required to obtain the IDNR construction permit. Although larger events result in significant overtopping flow (frontage road PG is roughly 1 foot below the minimum existing I-55 PG) design backwater attributed solely to this structure is roughly 2 feet.

Table 5 represents proposed, dual I-55 structures and the removal of the existing frontage road bridge without replacement. The 186-ft. +I- I-55 bridge length is configured with 18-foot wide berms flanking the channel and 1:2 slopewalls. This berm width is considered the minimum to maintain the same 10-year effective flow area beneath the proposed bridge as the existing bridge. The overbank berms call for excavation to 582.0 +I-, which is below natural overbank elevations. The excavation allows the proposed opening to exceed existing for all events equal to and greater than

Q10. A shorter structure without berms cannot satisfy that criteria. Some deposition can be expected here since the berm is lower than existing groundline. Consequently, to simulate the loss of effective overbank opening due to siltation, this same bridge length was modeled with berms placed at natural overbank elevations. Table 6 indicates the opening is reduced by roughly 6 – 7 %, while the design and regulatory headwaters were unchanged. The 186 ft. long structure with overbank excavation represents the shortest bridge length that is considered hydraulically adequate and also compliant with IDNR permit criteria.

Table 1 was developed for purposes of comparison. It demonstrates the bridge length required to eliminate Q100 backwater at I-55. The configuration does include overbank berms excavated to an elevation of 582.0. This table proposes a new frontage road structure the same length as the proposed I-55 bridge. It is our assumption that if the frontage road bridge is replaced, the rebuilt frontage road profile will be very similar to the interstate. It is our conclusion that adding a third identical bridge upstream of I-55 has the same impact on flood profiles as simply removing the existing upstream single span

Victor A. Modeer/Attn: W. E. Martens
Page 3
December 2, 2002

and regrading appropriately. For example, a comparison of tables 3 and 5 illustrates that three new bridges of the same length causes identical backwater to new dual I-55 bridges coupled with the removal of the frontage road bridge.

Regardless of the scope of improvement and the bridge length selected, we strongly recommend meeting the design policy's criteria regarding low beam clearance and roadway freeboard. Given the flooding history, the uncertainty of the design discharge estimation for this watershed and the interstate traffic volume, it is highly unlikely we would grant a waiver from policy for either the 2-ft. low beam clearance or the 3-ft. roadway freeboard criteria. Consequently, all of the proposed waterway tables indicate a low beam elevation of 593.0. Mike Cima of our Planning Unit informs us the District prefers a concrete beam type, which results in a superstructure depth of roughly 4.7 ft. With low beam at 593.0, PG at the structure will be approximately 597.7 +/- . This would constitute a grade raise of roughly 4 feet above existing at the bridge. The waterway tables indicate the PG away from the bridge could dip to an elevation roughly 1 ft. above existing low grade, and still satisfy the roadway freeboard criteria. Again, our analyses with three identical bridges (tables 1, 2 and 3) assume the frontage road will be raised up to match the eventual I-55 profile grade.

As mentioned above, we modeled the alternatives that we considered feasible based on our field check and discussions with your staff. However, the final approval of the hydraulics can only be made by IDNR-OWR through its issuance of the Individual Permit. We are including the HEC-RAS model should additional scenarios need to be analyzed. If you have any comments, questions, or would care to discuss our review, please contact Neil VanBebber at 558-4536.

NV/dla253

WATERWAY INFORMATION TABLE 1 (Prop I-55 & Prop US 66)

Route: I-55
 Section:
 County: Sangamon
 Date: 11/22/2002

S.N.: 084-0107, 084-0108
 S.N.: 084-0002 (US 66)
 Waterway: Brush Creek
 By: N. VanBebber

Created Head = 0

Drainage Area = 27.2 mi²

	Freq. Yr.	Q ft ³ /s	Opening - Exist.*	ft ² Prop.	Nat. H.W.E.	Head - Exist.	ft. Prop.	Headwater Elev. Exist.	@ Sta. C.L. Bridge
	10	2430	1021	1337	589.3	1.0	0.0	590.3	589.3
Design	50	3800	1021	1611	591.0	2.5	0.0	593.5	591.0
Base	100	4400	1021	1711	591.6	2.9	0.0	594.5	591.6
Max. Calc.	500	5840	1021	1946	593.0	2.7	0.2	595.7	593.2

10 Year Velocity through Existing Bridge = 2.4 fps

ALL-TIME H.W.E. & DATE: 595.4 06/06/2001

SCOPE OF WORK: Total removal and replacement of I-55 and US 66 bridges. Three new bridges with 0 created head.

* I-55 Existing Bridge Openings

10 Year Velocity through Prop. Bridge = 1.8 fps

S.N.: 084-0107, 084-0108
S.N.: 084-0002 (US 66)
Waterway: Brush Creek
By: N. VanBebber

Created Head = 0

PROPOSED STRUCTURE

TYPE: Open Abuts.
 LENGTH: 243' Bk. to Bk. Abuts.
 SPANS: 4
 L. BEAM: 593.0
 SKEW: 40

EXISTING STRUCTURE

TYPE: Open Abuts.
 LENGTH: 159' 8" Bk. to Bk. Abuts.
 SPANS: 3
 L. BEAM: 589.4
 SKEW: 40

NOTE: PROPOSED STRUCTURE DETAILS ARE PRELIMINARY, SUBJECT TO REFINEMENT IN TSL STAGE.

WATERWAY INFORMATION TABLE 2 (Prop I-55 with Prop US 66)

Route: I-55
 Section: Sangamon
 County: Sangamon
 Date: 11/22/2002

S.N.: 084-0107, 084-0108
 S.N.: 084-0002 (US 66)
 Waterway: Brush Creek
 By: N. VanBebber

Drainage Area = 27.2 mi²
 Existing Low Grade Elevation: 593.7 ft.
 Prop. Low Grade Elevation: 597.7 ft.
 @ Sta. C_L Bridge

Freq. Yr.	Q ft ³ /s	Opening - Exist. *	ft ²	Nat. H.W.E.	Head - Exist.	ft.	Headwater Elev. Prop.	C _L Bridge
10	2430	1011	1034	589.3	1.0	0.2	590.3	589.5
Design	50	3800	1021	1238	591.0	2.5	0.3	593.5
Base	100	4400	1021	1312	591.6	2.9	0.5	594.5
Max Calc.	500	5840	1021	1490	593.0	2.7	0.7	595.7

10 Year Velocity through Existing Bridge = 2.4 fps

ALL-TIME H.W.E. & DATE:

595.4

06/06/2001

594.3

05/13/2002

SCOPE OF WORK: Total removal and replacement of I-55 and US 66 bridges. Three new bridges.

* I-55 Existing Bridge Openings

PROPOSED STRUCTURE

TYPE:	Open Abuts.	TYPE:	Open Abuts.
LENGTH:	186'	Bk. to Bk. Abuts.	LENGTH: 159' 8"
SPANS:	3	SPANS: 3	Bk. to Bk. Abuts.
L. BEAM:	593.0	L. BEAM: 589.4	
SKEW:	40	SKEW: 40	

EXISTING STRUCTURE

TYPE:	Open Abuts.	TYPE:	Open Abuts.
LENGTH:	186'	Bk. to Bk. Abuts.	LENGTH: 159' 8"
SPANS:	3	SPANS: 3	Bk. to Bk. Abuts.
L. BEAM:	593.0	L. BEAM: 589.4	
SKEW:	40	SKEW: 40	

NOTE: PROPOSED STRUCTURE DETAILS ARE PRELIMINARY, SUBJECT TO REFINEMENT IN TSL STAGE.

WATERWAY INFORMATION TABLE 3 (Prop I-55 with Prop US 66)

Route: I-55
 Section: Sangamon
 County: Sangamon
 Date: 11/22/2002

S.N.: 084-0107, 084-0108
 S.N.: 084-0002 (US 66)
 Waterway: Brush Creek
 By: N. VanBebber

Existing Low Grade Elevation: 592.0 ft.

Prop. Low Grade Elevation: 597.7 ft.

@ Sta. C_L Bridge

Drainage Area =	27.2	mi ²	Opening -	ft ²	Nat.	Head -	ft.	Headwater Elev.	@ Sta. C _L Bridge
	Freq.	Q	Exist. *	Prop.	H.W.E.	Exist.	Prop.	Exist.	Prop.
	Yr.	ft ³ /s							
Design	10	2430	511	1034	589.3	1.0	0.2	590.3	589.5
Base	50	3800	511	1238	591.0	2.5	0.3	593.5	591.3
Max. Calc.	100	4400	511	1312	591.6	2.9	0.5	594.5	592.1
	500	5840	511	1490	593.0	2.7	0.7	595.7	593.7

10 Year Velocity through Existing Bridge = 4.8 fps

ALL-TIME H.W.E. & DATE:

595.4

06/06/2001

10 Year Velocity through Prop. Bridge =

594.3

05/13/2002

SCOPE OF WORK: Total removal and replacement of I-55 and US 66 bridges. Three new bridges.

* US 66 Existing Bridge Opening

PROPOSED STRUCTURE

TYPE:	Open Abutts.
LENGTH:	186'
SPANS:	3
L. BEAM:	593.0
SKEW:	40

EXISTING STRUCTURE

TYPE:	Closed Abutts.
LENGTH:	73' 0"
SPANS:	3
L. BEAM:	587.5
SKEW:	40

NOTE: PROPOSED STRUCTURE DETAILS ARE PRELIMINARY; SUBJECT TO REFINEMENT IN TSL STAGE.

WATERWAY INFORMATION TABLE 4 (Prop I-55 with Exist US 66)

Route: I-55
 Section: Sangamon
 County: 11/21/2002
 Date: N. VanBebber

S.N.: 084-0107, 084-0108
 S.N.: 084-0002 (US 66)
 Waterway: Brush Creek
 By:

Drainage Area = 27.2 mi² Prop. Low Grade Elevation: 592.0 ft. @ Sta. C_L Bridge

Freq. Yr.	Q ft ³ /s	Opening -		Nat. H.W.E.	Head - ft.	@ Sta. C _L Bridge
		Exist.*	Prop.			
10	2430	511	1034	589.3	1.0	590.3
Design	50	3800	511	1238	2.5	593.5
Base	100	4400	511	1312	2.9	594.5
Max. Calc.	500	5840	511	1490	2.7	596.3

10 Year Velocity through Existing Bridge = 4.8 fps 10 Year Velocity through Prop. Bridge = 2.4 fps

ALL-TIME H.W.E. & DATE:

SCOPE OF WORK: Total removal and replacement of I-55 bridges. Existing US 66 Bridge remains in place. Two new bridges.
 * US 66 Existing Bridge Opening

PROPOSED STRUCTURE

TYPE:	Open Abutts.
LENGTH:	186'
SPANS:	3
L. BEAM:	593.0
SKEW:	40

EXISTING STRUCTURE

TYPE:	Closed Abutts.
LENGTH:	73' 0"
SPANS:	3
L. BEAM:	587.5
SKEW:	40

NOTE: PROPOSED STRUCTURE DETAILS ARE PRELIMINARY; SUBJECT TO REFINEMENT IN TSL STAGE.

WATERWAY INFORMATION TABLE 5 (Prop I-55 w/o US 66)

Route: I-55
 Section:
 County: Sangamon
 Date: 11/22/2002

S.N.: 084-0107, 084-0108
 S.N.: 084-0002 (US 66)
 Waterway: Brush Creek
 By: N. VanBebber

Drainage Area = 27.2 mi²

	Existing	Low Grade Elevation:	593.7 ft.	@ Sta.	C _L Bridge
	Prop.	Low Grade Elevation:	597.7 ft.	@ Sta.	C _L Bridge
Freq.	Q	Opening - ft ²	Nat. H.W.E.	Head - ft.	Headwater Elev.
Yr.	ft ³ /s	Exist.	Prop.	Exist.	Prop.

	10	2430	1011	1034	589.3	1.0	0.2	590.3	589.5
Design	50	3800	1021	1238	591.0	2.5	0.3	593.5	591.3
Base	100	4400	1021	1312	591.6	2.9	0.5	594.5	592.1
Max. Calc.	500	5840	1021	1490	593.0	2.7	0.7	595.7	593.7

10 Year Velocity through Existing Bridge = 2.4 fps

ALL-TIME H.W.E. & DATE:

595.4 06/06/2001

SCOPE OF WORK: Removal of US bridge and Total Removal and Replacement of I-55 bridges. Two new bridges.
 * I-55 Existing Bridge Openings

PROPOSED STRUCTURE

TYPE:	Open Abutts.	TYPE:	Open Abutts.
LENGTH:	186'	Bk. to Bk. Abutts.	LENGTH: 159' 8"
SPANS:	3	SPANS: 3	Bk. to Bk. Abutts.
L. BEAM:	593.0	L. BEAM: 589.4	
SKEW:	40	SKEW: 40	

EXISTING STRUCTURE

TYPE:	Open Abutts.	TYPE:	Open Abutts.
LENGTH:	186'	Bk. to Bk. Abutts.	LENGTH: 159' 8"
SPANS:	3	SPANS: 3	Bk. to Bk. Abutts.
L. BEAM:	593.0	L. BEAM: 589.4	
SKEW:	40	SKEW: 40	

NOTE: PROPOSED STRUCTURE DETAILS ARE PRELIMINARY, SUBJECT TO REFINEMENT IN TSL STAGE.

WATERWAY INFORMATION TABLE 6 (Prop I-55 with Prop US 66)

Route: I-55
 Section: Sangamon
 County: Sangamon
 Date: 11/22/2002
 S.N.: 084-0107, 084-0108
 S.N.: 084-0002 (US 66)
 Waterway: Brush Creek
 By: N. VanBebber

Overbank berms at 585.0

Existing Low Grade Elevation: 593.7 ft. @ Sta. C_L Bridge

Drainage Area =	27.2 mi ²	Prop. Low Grade Elevation:	597.7 ft.	@ Sta. C _L Bridge				
	Freq. Yr.	Q ft ³ /s	Opening - Exist. *	Nat. H.W.E.	Head - ft.	Headwater Elev.	Prop. Exist.	Prop.
Design	10	2430	1011	948	589.3	1.0	0.2	590.3
Base	50	3800	1021	1154	591.0	2.5	0.3	593.5
Max. Calc.	100	4400	1021	1229	591.6	2.9	0.5	594.5
	500	5840	1021	1406	593.0	2.7	0.7	595.7

10 Year Velocity through Existing Bridge = 2.4 fps 10 Year Velocity through Prop. Bridge = 2.6 fps

ALL-TIME H.W.E. & DATE:

595.4 06/06/2001

594.3 05/13/2002

SCOPE OF WORK: Total removal and replacement of I-55 and US 66 bridges. Overbank berms at 585.0 Three new bridges.

* I-55 Existing Bridge Openings

PROPOSED STRUCTURE

TYPE:	Open Abuts.
LENGTH:	186'
SPANS:	3
L. BEAM:	593.0
SKEW:	40

EXISTING STRUCTURE

TYPE:	Open Abuts.
LENGTH:	159' 8"
SPANS:	3
L. BEAM:	589.4
SKEW:	40

NOTE: PROPOSED STRUCTURE DETAILS ARE PRELIMINARY; SUBJECT TO REFINEMENT IN TSL STAGE.

WATERWAY INFORMATION TABLE 7 (Prop I-55 with Exist US 66)

Route: I-55
 Section: Sangamon
 County: Sangamon
 Date: 11/21/2002

Overbank berms at 585.0.

S.N.: 084-0107, 084-0108
 S.N.: 084-0002 (US 66)
 Waterway: Brush Creek
 By: N. VanBebber

Drainage Area = 27.2 mi² Existing Low Grade Elevation: 592.0 ft. @ Sta. C_L Bridge

	Freq. Yr.	Q ft ³ /s	Opening - Exist.*	ft ²	Nat. H.W.E.	Head - Exist.	ft.	Headwater Elev. Exist.	Prop.	Prop.	@ Sta. C _L Bridge
Design	10	2430	511	948	589.3	1.0	1.0	590.3	590.3	590.3	
Base	50	3800	611	1154	591.0	2.5	2.3	593.5	593.3		
Max. Calc.	100	4400	511	1229	591.6	2.9	2.8	594.5	594.4		
	500	5840	511	1406	593.0	2.7	3.3	595.7	596.3		

10 Year Velocity through Existing Bridge = 4.8 fps 10 Year Velocity through Prop. Bridge = 2.6 fps

ALL-TIME H.W.E. & DATE:

SCOPE OF WORK: Total removal and replacement of I-55 bridges. Existing US 66 Bridge remains in place. Two new bridges.
 * US 66 Existing Bridge Opening

PROPOSED STRUCTURE

TYPE:	Open Abutts.
LENGTH:	186'
SPANS:	3
L. BEAM:	593.0
SKEW:	40

EXISTING STRUCTURE

TYPE:	Closed Abutts.
LENGTH:	73' 0"
SPANS:	3
L. BEAM:	587.5
SKEW:	40

NOTE: PROPOSED STRUCTURE DETAILS ARE PRELIMINARY; SUBJECT TO REFINEMENT IN TSU STAGE.

Attachment H

Proposed Plan and Profile

Attachment I
Abbreviated Existing Plans